







C	A	P	N	0164	F01	V01
---	---	---	---	------	-----	-----

Date : 24th June 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1A), (1B), (2) & (3)	Motor Vehicle width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (1A), (2), (3), (4), (5), & (6) Radial, Tubeless	Size & ply rating of tyres		IS-15633:2005, AIS-051:2004, AIS-142:2019	
		Front / Rear	205/65 R16 95H		Bridgestone Apollo MRF
	(7)	Temporary Tyre	T 135/90 R16	CEAT	AIS-110 : 2009
	(8)	Tyre pressure monitoring system		AIS-154	
96	(1), (2), (3), (4)(ii), (4B), (7)(a) & (8)	Brakes		IS-15986:2015	
	(10)	Electronic Stability Control (ESC)		AIS: 133-2016	
	(11)	Brake assist System (BAS)		AIS: 152:2018	
96B	(a) & (b)	High Speed Brake Requirements		IS-15986:2015	
98	(3)	Steering gear		IS-11948:2010	
	(1), (2)			IS-12222:2011	
99	-	Forward and backward motion		-	
100	(1), (2) & (3) & (3c)	Safety glass		IS-2553(Part 2)(Rev. 1): 2019	
101	(1) & (2)	Windscreen wiper		IS-15804:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1) (a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
114	(1) & (2)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(ii), (18)(i)	Emission of smoke, vapour, etc. from motor vehicle		AIS-137	
ICAT Ref No.	2023 - 0469 (IOCS No: 167529)				
Emission Report No.	CTOPS 0348 dt. 23.02.2023				
Noise Report No.	CT1VS 0278 dt. 22.02.2023				
Horn Inst. Report No.	CTOVN 1611 dt. 11.10.2018				
FTP Report No.	CTOES 0028 dt. 19.01.2023				

AUTHORISED SIGNATORY

			
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER		SAURABH DALELA DIRECTOR	Page 2 of 6