



C A S N 0706

Date : 24th July 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B) & (2)	Motor Vehicle Width, Length & Height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4); (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front	80/100-18 M/C 47P		TVS, MRF, CEAT, MAXXIS
		Rear	80/100-18 M/C 54P		TVS, MRF, CEAT, MAXXIS
96	(1), (2), (3), (4)(ib), (4A), (7)(c) & (8)	Brakes with CBS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111		Prohibition of spotlights etc.		-	
114	(1) & (2)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(i), (19)(i)	Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (Including OBD IIA))		AIS 137	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (≤ 7 kW)		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	94.5 dB(A)	
			Performance		IS 1884:1993
120	(1) (2)	Pass by Noise	Silencers		IS 3028:1998
			Limit :	77 dB(A) ($80 < cc \leq 175$)	
			Observed :	71.6 dB(A) / 72.2 dB(A)	
122	(1) & (2)	Embossment of chassis number & engine number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle (Pillion Hand Hold)		IS 14495:1998	
123	(2)	Safety devices in motor cycle (Footrest)		AIS 148:2018	
123	(4)	Safety devices in motor cycle (Stand)		AIS 146:2018	
123	(5)	Safety devices in motor cycle (External Projection)		AIS 147:2018	
ICAT Ref No.	2023-0456 [IOCS No. : 166180]				
Emission Report No.	CTOPS 0838 Dt:24.07.2023				
FTP Report No.	CTOES 0347 Dt. 20.07.2023				
Noise Report No.	CTOVS 1178 Dt. 21.07.2023				
Horn Inst. Report No.	CT1VQ 0753 Dt. 13.07.2021				

AUTHORISED SIGNATORY

MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER		SAURABH DALELA DIRECTOR	Page 2 of 4