








C	A	S	N	0008	V01
---	---	---	---	------	-----

Date : 07th August 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2) & (3)	Motor Vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (1A), (2), (3), (4), (5) & (6) (Tubeless & Radial)	Size & ply rating of tyres		IS-15633:2005, AIS-051:2004 AIS-142:2019	
		Front / Rear	195/60 R16 89V & 195/60 R16 89H		1. Ceat, India 2. MRF, India
		Temporary Use Spare Wheel	185/65R15 88R & 165/80R14 85R		1. Ceat, India
	(8)	Tyre pressure monitoring system		AIS 154	
96	(1), (2), (3), (4)(ii), (4B), (7)(a) & (8)	Brakes		IS-15986:2015	
	(10)	Electronic Stability Control		AIS-133:2016	
	(11)	Brake assist System		AIS-152:2018	
96B	(a) & (b)	High Speed Brake Requirements		IS-15986:2015	
98	(3)	Steering gear		IS-11948:2010	
	(1), (2)			IS-12222:2011	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (3c)	Safety glass		IS 2553 (Part 2)(Rev.1) :2019	
101	(1) & (2)	Windscreen wiper		IS-15804:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1) (a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
114	(1) & (2)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(i), 18(i)	Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (OBD II)		AIS-137	
115G	(1) & (2)	Fuel Consumption Standard		AIS-137	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1)	Speed Govenner (SLF in ECU)		NA	

ICAT Ref No.	2023 - 0873 (IOCS No. 168267)
Emission Report No.	CT0PR 1167 dt. 06.12.2022
Noise Report No.	CT0VR 1687 dt. 29.11.2022
FTP Report No.	CT0ER 0507 dt. 14.12.2022
Horn Inst. Report No.	CT0VP 0588 dt. 27.08.2020, CT1VQ 1466 dt. 13.12.2021

AUTHORISED SIGNATORY				
				
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER			SAURABH DALELA DIRECTOR	Page 2 of 6