




C	A	S	B	0127	F01	V01
---	---	---	---	------	-----	-----

Date : 10th October 2023




ANNEXURE - II

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2) & (3)	Motor vehicles width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5), (6) (Radial / with tube)	Size & ply rating of tyres		IS-15636-2012 & AIS-051:2004	
		Front	12.00R-20 (Single)		MRF / Apollo / JK tyre
		Rear	12.00R-20 (Dual)		
96	(1), (2), (3), (4), (7)(a), (8) & (9)	Brakes with ABS		IS 11852 : 2013	
98	(1), (2), (3) & (5)(b)	Steering Gear		IS-12222:2011	
		Steering Effort		IS-11948:2010	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (3c)	Safety glass		IS 2553 (Part 2) (Revision 1): 2019	
101	(1) & (2)(ii)	Windscreen wiper		IS 15802:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1)(ii) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010 & AIS-090-2005	
105	(1)(a), (2), (3), (4), (5) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1)	Speed Governor		AIS-018-2001	



ICAT Ref No.	2023-0103 (IOCS Ref: 166119)
Net Power Test Report No.	CT0ER 0475 dt. 28.11.2022, CT0ES 0439 dt. 20.09.2023
Noise Report No.	CT0VR 1648 dt. 22.11.2022
Horn Inst. Report No.	CT0VR 1644 dt. 22.11.2022

AUTHORISED SIGNATORY

			
VIKAS SADAN DEPUTY GENERAL MANAGER		SAURABH DALELA DIRECTOR	Page 2 of 6