



C A S B 0953

Date : 02nd November 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard		
93	(1)(A), (1)(B) & (2)	Motor vehicle width, length and height			-		
94	(1), (2) & (3)	Condition of tyres			-		
95	(1), (2), (3), (4), (5) & (6) (Tubeless, Radial)	Front	145R12LT 86/84E8PR 145R12LT 86/84Q8PR	M/s Ceat Ltd. M/s MRF Ltd.	IS 15627:2005 & AIS-050:2004		
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	Brakes			IS 14664:2010		
98	(1), (2) & (3)	Steering gear			NA		
99	--	Forward and backward motion			-		
100	(1), (2), (3), (3c)	Safety glass			IS 2553: (Part 2) 2019		
101	(1)	Windscreen wiper			-		
102	(1) & (2)	Signaling devices, direction indicators and stop lights			-		
103	(1)	Position of the indicator			-		
104	(1)(v) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010 & AIS:090-2005		
105	(1)(b), (3), (4), (5) & (7)	Lamps			-		
106	(1)	Deflection of lights			-		
108	(1)	Use of red or white lights			-		
109	--	Parking Lights			-		
110	--	Lamps on 3 Wheelers			AIS-134:2016		
111	-	Prohibition of spotlights etc.			-		
117	(1) & (2)	Speedometer			IS 11827:2008		
119	(1) & (2)	Horns	Installation		IS 15796:2008		
			Limit :	87 dB(A) to 112 dB(A)			
			Observed :	93 dB(A)	IS 1884:1993		
120	(2)	Pass by Noise	Limit : Observed :	77 dB(A) 61 dB(A)	IS 3028:1998		
ICAT Ref No.	2023-0655 (IOCS: 167415)						
Power Report No.	CT0ES 0404 dt. 17.08.2023						
Noise Report No.	CT1VS 1641 dt. 12.10.2023						
Horn Inst. Report No.	ARAI/SHL/CT/APX-2021-25130/0540 dt. 16.02.2021						
AUTHORISED SIGNATORY							
VIKAS SADAN DEPUTY GENERAL MANAGER			SAURABH DALELA DIRECTOR				
Page 2 of 4							