







C	A	S	N	0312	V01
---	---	---	---	------	-----

Date : 09<sup>th</sup> November 2023

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B) & (2)	Motor Vehicle Width, Length & Height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4); (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front	100/80-17M/C 52P		MRF
		Rear	140/60R17M/C 63P		
96	(1), (2), (3), (4)(ib), (4A), (7)(c) & (8)	Brakes with ABS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111		Prohibition of spotlights etc.		-	
114	(1) & (2)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(i), (19) (i)	Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (Including OBD II B))		AIS 137	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Above 7kW)		IS 15796:2008
			Limit :	87 dB(A) to 112 dB(A)	
			Observed :	99.8 dB(A)	
120	(1)	Pass by Noise	Performance		IS 1884:1993
			Limit :	80 dB(A) (Greater Than 175 cc)	
			Observed :	70.9 dB(A)	
122	(1) & (2)	Embossment of chassis number & engine number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle (Pillion Hand Hold)		IS 14495:1998	
	(2)	Safety devices in motor cycle (Footrest)		AIS 148:2018	
	(4)	Safety devices in motor cycle (Stand)		AIS 146:2018	
	(5)	Safety devices in motor cycle (External Projection)		AIS 147:2018	
<b>ICAT Ref No.</b>		2023-1330; [IOCS No. : 169097]			
<b>Emission Report No.</b>		CTOPS 0438 dt. 17.03.2023			
<b>FTP Report No.</b>		CTOER 0472 dt. 24.11.2022			
<b>Noise Report No.</b>		CTOVS 0088 dt. 18.01.2023			
<b>Horn Inst. Report No.</b>		CTOVQ 0250 dt. 25.02.2021			

**AUTHORISED SIGNATORY**

			
<p><b>VIKAS SADAN</b> DEPUTY GENERAL MANAGER</p>		<p><b>SAURABH DALELA</b> DIRECTOR</p>	<p>Page 2 of 4</p>