







C A S B 0984

ANNEXURE - I

Date : 10<sup>th</sup> November 2023

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2) & (3)	Motor vehicles width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS-15636-2012 & AIS-051:2004	
		Front	215/75 R17.5 14PR (Single)		M/s JK Tyre & Industries Ltd, CEAT, Apollo
		Rear	215/75 R17.5 14PR (Dual)		
96	(1), (2), (3), (4)(ii), (7)(a), (8) & (9)	Brakes with ABS		IS 11852 : 2013	
98	(1), (2), (3)	Steering Gear		IS-12222:2011	
		Steering Effort		IS-11948:2010	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (3c)	Safety glass		IS 2553 (Part 2) (Revision 1): 2019	
101	(1) & (2)(ii)	Windscreen wiper		IS 15802:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1), (2), (4) & (5)	Fitment of reflectors		AIS-057 (Rev. 1):2010, AIS 90 (Rev. 1):2019	
105	(1) (a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1)	Speed Governor		AIS-018:2001	

ICAT Ref No.	2023-0176 (IOCS Ref: 166696)
Motor Report No.	CT0ES 0196 dt. 05.04.2023
Noise Report No.	CT0VS 1531 dt. 14.09.2023
Horn Inst. Report No.	CT0VS 1613 dt. 06.10.2023

<b>AUTHORISED SIGNATORY</b>			
			
<b>VIKAS SADAN</b> DEPUTY GENERAL MANAGER		<b>SAURABH DALELA</b> DIRECTOR	Page 2 of 6