



C A S B 1016

Date : 12th December 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), 1(B), (2)	Motor vehicle width, length and height			-
94	(1), (2) & (3)	Condition of tyres			-
95	(1), (2),(3), (4), (5) & (6) (Front / Rear - Tubetype)	Size & ply rating of tyres 4.00-8, 76E 6PR	Make M/s. Apollo	IS 15627:2005 & AIS-050:2004	
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	Brakes			IS 14664:2010
98	(1), (2) & (3)	Steering gear			NA
99	--	Forward and backward motion			-
100	(1), (2) & (3)	Safety glass			IS 2553:1992 (Part 2)
101	(1) & 2(iii)	Windscreen wiper			IS 15802:2008
102	(1), (2)	Signaling devices, direction indicators and stop lights			-
103	(1) & (2)	Position of the indicator			-
104	1(v) & (4)	Fitment of reflectors & Reflective tapes			AIS-057 (Rev. 1): 2010 & AIS:090-2005
105	(1)(b), (3),(4), (5) & (7)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
109	--	Parking Lights			-
110	--	Lamps on 3 Wheelers			AIS-134:2016
111	-	Prohibition of spotlights etc.			-
117	(1) & (2)	Speedometer			IS 11827:2008
119	(1) & (2)	Horns	Installation		IS 15796:2008
			Limit :	87 dB(A) to 112 dB(A)	
			Observed :	89.8 dB(A)	
			Performance		IS 1884:1992
120	(2)	Pass by Noise	Limit :	77 dB(A)	IS 3028:1998
			Observed :	69 dB(A)	
ICAT Ref No.	2023-0781 (IOCS: 168600)				
Power Report No.	CT0PS 0971 dt. 22.09.2023				
Noise Report No.	CT0VS 1930 dt. 08.12.2023				
ICAT Ref No.	2023-0781 (IOCS: 168600)				

Horn Inst. Report No. CI

Vikas Sodaw
—
Pragya Energy Solutions
FRW Zero

VIKAS SADAN
DEPUTY GENERAL MANAGER



21 Renewal
ns Private L. 11
te Energy Solutions P
TER Is 2



Page 2 of
4