



C	A	S	B	1019
---	---	---	---	------

Date : 13th December 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			-	
94	(1), (2), (3)	Condition of tyres			-	
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050-2004	
		Front/Rear	3.75-12, 66B	CEAT		
			3.75-12, 66B	Ralson		
			3.75-12, 60J	TVS Srichakra		
			3.75-12, 66E	MRF		
96	(1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999	
99	-	Forward and backward motion			-	
100	(1), (2), (3)	Safety glass			IS 2553(Part 2)(Rev. 1):2019	
101	(1)	Windscreen Wiper			IS 15802-2008	
102	(1), (2)	Signaling devices, direction indicators and stop lights			-	
103	(1), (2)	Position of the indicator			-	
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057(Rev.1):2010 & AIS090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps			-	
106	(1)	Deflection of lights			-	
108	(1)	Use of red or white lights			-	
109	-	Parking lights			-	
110	-	Lamps for three wheelers			-	
111	-	Prohibition of spotlights etc.			-	
119	(1) & (2)	Horns	Installation		IS 15796:2008	
			Limit :	83 dB(A) to 112 dB(A)		
			Observed :	85.5 dB(A)		
122	(1) & (2)		Performance			
			Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			
			Safety standards of components as applicable			
124	-		Refer ANNEXURE - IA & IB			
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-1)Rev.1:2011	
			Installations		AIS-002 (Part-1)Rev.1:2011	

ICAT Ref No.	2023- 0631 (168030)
Power Test Report No.	CTOPS 0826 dt. 19.07.2023 & CT0ES 0230 dt. 20.04.2023
Horn Inst. Report No.	CT0VS1697 dt. 20.10.2023

AUTHORISED SIGNATORY			
VIKAS SADAN DEPUTY GENERAL MANAGER	INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR	SAURABH DALELA DIRECTOR	Page 2 of 3