



C	A	S	B	1020
---	---	---	---	------

Date : 13th December 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Front/ Rear	Size & ply rating of tyres	Make	IS.15627:2005 & AIS-050-2004
			3.75-12 66B	CEAT	
			90/90-12 64B	CEAT	
			90/90-12 54J	TVS	
			3.75-12 60J	TVS	
			90/90-12 54J	POWERMAX	
			3.75-12 60J	POWERMAX	
			3.75-12 66E	APOLLO	
3.75-12 66E	MRF				
3.75-12 66B	PODDAR				
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1), (2), (3)	Safety glass		NA	
101	(1)	Windscreen Wiper		NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1), (2)	Position of the indicator		-	
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		105.1 dB(A) / 94.6 dB(A) @ 12.9 V
			Performance	IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part-2)Rev.1:2011	
		Mirror	Installation	AIS-002 (Part-2)Rev.1:2011	

ICAT Ref No.	2023-0673 (168161)
Power Test Report No.	CTOPS 0893 dt. 10.08.2023 & CT0ES 0230 dt. 20.04.2023
Horn Inst. Report No.	CTOVS 1829 dt. 08.11.2023

AUTHORISED SIGNATORY

 VIKAS SADAN DEPUTY GENERAL MANAGER	 ICAT INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR • AUTOMOTIVE	 SAURABH DALELA DIRECTOR	 Page 2 of 3
---	---	---	---