



C	A	P	B	0092	F01	V01
---	---	---	---	------	-----	-----

Date : 13<sup>th</sup> December 2023

## ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004
		Front/ Rear	Make	
		3.75-12, 66B	CEAT	
		3.75-12, 66E	MRF	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1), (2), (3)	Safety glass		IS 2553(Part 2)(Rev.1):2019
101	(1)	Windscreen Wiper		IS 15802-2008
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Installation		IS 15796:2008
		Limit :	83 dB(A) to 112 dB(A)	
		Observed :	98.6 dB(A)	
		Performance		IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View	Specifications	AIS-001 (Part-1)Rev.1:2011
		Mirror	Installation	AIS-002 (Part-1)Rev.1:2011

ICAT Ref No.	2023-1513 (IOCS: 171770)
Power Test Report No.	CT0PO 1248 dt 31.12.2019
Horn Inst. Report No.	CT1VS 1048 dt. 23.06.2023

AUTHORISED SIGNATORY

			
<b>VIKAS SADAN</b> DEPUTY GENERAL MANAGER		<b>SAURABH DALELA</b> DIRECTOR	Page 2 of 3