







C A S B 0042

Date : 13<sup>th</sup> January 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2) & (3)	Motor vehicles width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Radial & tubeless)	<b>Size &amp; ply rating of tyres</b>		IS-15636-2012, AIS-051:2004	
		Front (Single)	295/80 R22.5, 16PR		MRF JK Tyre
			295/80 R22.5, 18PR		CEAT Michelin
		Rear (Dual)	295/80 R22.5, 16PR		MRF JK Tyre
295/80 R22.5, 18PR	CEAT Michelin				
96	(1), (2), (3), (4), (7)(a) & (8)	Brakes		IS 11852 : 2013	
98	(1), (2), (3) & (4)	Steering Gear		IS-12222:2011	
		Steering Effort		IS-11948:2010	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (3)(C)	Safety glass		IS 2553 (Part 2) (Revision 1): 2019	
101	(1) & (2)	Windscreen wiper		IS 15802:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010, AIS 90:2019	
105	(1) (a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1)	Speed Governor		(Not applicable)	

<b>ICAT Ref No.</b>	2023 - 1417 (IOCS Ref: 171252)
<b>Net Power Test Report No.</b>	CT0ER 0392 dt. 06.10.2022
<b>Noise Report No.</b>	CT0VT 0025 dt. 12.01.2024
<b>Horn Inst. Report No.</b>	CT0VT 0022 dt. 12.01.2024

<b>AUTHORISED SIGNATORY</b>					
	<b>VIKAS SADAN</b> DEPUTY GENERAL MANAGER	<b>SAURABH DALELA</b> DIRECTOR			
					Page 2 of 6