



C A S N 0200 V01

Date : 30th January 2024

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | | Standard |
|----------|--|--|---------------|-------------------------------|--|
| 93 | (1)(A), (1)(B), (2) & (3) | Motor Vehicle width, length and height | | | - |
| 94 | (1), (2) & (3) | Condition of tyres | | | - |
| 95 | (1), (2), (3), (4), (5), & (6) (Radial/ Tubeless) | Size & ply rating of tyres | | Make | IS-15633:2005, AIS-051:2004 & AIS-142:2019 |
| | | Front / Rear/ Spare | 215/55R17 94V | Goodyear/ Apollo | |
| | | Front / Rear | 215/55R18 95H | Goodyear/Continental/ Ceat | |
| | | Temporary use Spare Wheel | 215/60R17 96H | Goodyear/ Apollo | |
| | (8) | Tyre pressure monitoring system | | | AIS 154 : 2018 |
| 96 | (1), (2), (3), (4)(ii), (4B), (7)(a) & (8) | Brakes | | | IS-15986:2015 |
| | (10) | Electronic Stability Control (ESC) | | | AIS 133:2016 |
| | (11) | Brake assist System (BAS) | | | AIS 152:2018 |
| 96B | (a) & (b) | High Speed Brake Requirements | | | IS-15986:2015 |
| 98 | (3) | Steering gear | | | IS-11948:2010 |
| | (1), (2) | | | | IS-12222:2011 |
| 99 | - | Forward and backward motion | | | - |
| 100 | (1), (2), (3) & (3c) | Safety glass | | | IS-2553 (Part 2)(Rev.1):2019 |
| 101 | (1) & (2) | Windscreen wiper | | | IS-15804:2008 |
| 102 | (1) & (2) | Signalling devices, direction indicators and stop lights | | | - |
| 103 | (1) & (2) | Position of the indicator | | | - |
| 104 | (1) & (4) | Fitment of reflectors | | | AIS-057 (Rev. 1): 2010 |
| 105 | (1) (a), (2), (4) & (7) | Lamps | | | - |
| 106 | (1) | Deflection of lights | | | - |
| 108 | (1) | Use of red or white lights | | | - |
| 109 | - | Parking light | | | - |
| 111 | - | Prohibition of spotlights etc. | | | - |
| 115G | (1) & (2) | Fuel Consumption Standard | | | AIS 137 |
| 117 | (1) & (2) | Speedometer | | | IS-11827:2008 |
| 118 | (1) | Speed Governor | | | NA |

| | |
|-----------------------|--|
| ICAT Ref No. | 2023-1824; [IOCS No. 172852] |
| Emission Report No. | CT0PS 0329 Dt. 22.02.2023 |
| FTP Report No. | CT0EP 0014 Dt. 09.01.2020 |
| Noise Report No. | CT0VR 1341 Dt. 27.09.2022 |
| Horn Inst. Report No. | CT0VO 0431 Dt. 09.04.2019, CT0VP 0132 Dt. 07.02.2020 & CT0VP 1333 Dt. 26.09.2022 |

| AUTHORISED SIGNATORY | | | |
|-------------------------------|--|----------------------------|-------------|
| | | | |
| JAYWANT HARDIKAR HEAD-CMVR | | SAURABH DALELA DIRECTOR | Page 2 of 6 |