



C A T B 0160




Date : 16th February 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B) & (2)	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tube Type - Diagonal)	Front	4.50-10 8PR 85 E	M/s ZAHI TYRES M/s TVS Srichakra	IS 15627:2005 & AIS-050:2004
		Rear			
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	Brakes		IS 14664:2010	
98	(1), (2) & (3)	Steering gear		NA	
99	---	Forward and backward motion		-	
100	(1), (2), (3), (3c)	Safety glass		IS 2553: (Part 2) 2019	
101	(1)	Windscreen wiper		-	
102	(1) & (2)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1)(v) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010 & AIS:090-2005	
105	(1)(b), (3), (4), (5) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	---	Parking Lights		-	
110	---	Lamps on 3 Wheelers		AIS-134:2016	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		87 dB(A) to 112 dB(A)
			Observed :		89 dB(A)
			Performance	IS 1884:1993	
120	(2)	Pass by Noise	Limit :	77 dB(A)	IS 3028:1998
			Observed :	63 dB(A)	

ICAT Ref No. 2023-0363 (IOCS: 167223)
 Power Report No. ARAI/AED/20212022/3100011477/CT/5140 Dt.02.12.2021
 Noise Report No. CT0VT 0220 dt. 10.02.2024
 Horn Inst. Report No. CT0VT 0221 dt. 10.02.2024

AUTHORISED SIGNATORY

 JAYWANT HARDIKAR HEAD-CMVR		 SAURABH DALELA DIRECTOR	 Page 2 of 4
---	---	---	--