



C A T B 0202

Date : 29th February 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard		
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			-		
94	(1), (2), (3)	Condition of tyres			-		
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050-2004		
		3.75-12, 66E		MRF			
		Front/ Rear	3.75-12, 66B	Ralson			
96	(1), (2), (3), (4)(i), (7)(b)		3.75-12, 67B	CEAT			
			Brakes		IS 14664:1999		
			Forward and backward motion		-		
100	(1), (2), (3)	Safety glass			IS 2553 (Part 2) (Rev.1): 2019		
101	(1)	Windscreen Wiper			-		
102	(1), (2)	Signaling devices, direction indicators and stop lights			-		
103	(1), (2)	Position of the indicator			-		
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057(Rev.1):2010 & AIS090-2005		
105	(1)(b), (3), (4), (5), (7)	Lamps			-		
106	(1)	Deflection of lights			-		
108	(1)	Use of red or white lights			-		
109	-	Parking lights			-		
110	-	Lamps for three wheelers			-		
111	-	Prohibition of spotlights etc.			-		
119	(1) & (2)	Horns	Installation		IS 15796:2008 Amd.3 : 2019		
			Limit :	83 dB(A) to 112 dB(A)			
			Observed :	102.9 dB(A)			
Performance			IS 1884:1993				
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065-2005		
124	-	Safety standards of components as applicable			Refer ANNEXURE - IA & IB		
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-1) Rev.1:2011		
			Installation		AIS-002 (Part-1) Rev.1:2011		

ICAT Ref No.	2023-0596 (168171)		
Power Test Report No.	CTOPT 0181 dt. 09.02.2024 & CT0ER 0446 dt. 15.11.2022		
Horn Inst. Report No.	CT0VT 0057 dt. 19.01.2024		
AUTHORISED SIGNATORY			
JAYWANT HARDIKAR HEAD-CMVR		 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY MANESAR	  Integration • Service • Excellence
SAURABH DALELA DIRECTOR			Page 2 of 3