



C A T B 0346

Date : 29nd March 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004	
		Front/ Rear	Make		RALSON
			90/90-12 54L(Tube less), 3.0-12 63B (Tube type /Tube type) & 3.75-12 66B(Tube type /Tube type)		
			90/90-12,64B & 3.75-12, 66B(Tube type)		CEAT
90/90-12, 54J & 3.75 x 12, 60J (Tube type)	TVS				
		3.75-12,66B (Tube type)	MRF		
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1),(2),(3)	Safety glass		IS 2553(Part 2)(Rev.1):2019	
101	(1)	Windscreen Wiper		-	
102	(1), (2)	Signaling devices, direction indicators and stop lights		NA	
103	(1), (2)	Position of the indicator		-	
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS-090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		88.6 dB(A)
			Performance	IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref. Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part-1)Rev.1:2011	
		Mirror	Installation	AIS-002 (Part-1)Rev.1:2011	

ICAT Ref No.	2022 -1087 (IOCS: 169934)
Power Test Report No.	CTOES 0252 Dt.10.05.2023 &CTOPS 1044 Dt.07.11.2023
Horn Inst. Report No.	CTOVT 0020 Dt. 12.01.2024

AUTHORISED SIGNATORY			
JAYWANT HARDIKAR HEAD -CMVR		SAURABH DALELA DIRECTOR	Page 2 of 3