



C A T B 0508

Date : 22nd May 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard		
93	(1)(A), 1(B), 2	Motor vehicle width, length and height			-		
94	(1), (2) & (3)	Condition of tyres			-		
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Front / Rear	Size & ply rating of tyres 4.50-10 85E 8PR	Make 1. CEAT 2. RALSON	IS 15627:2005 & AIS-050:2004		
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	Brakes			IS 14664:2010		
98	(1), (2) & (3)	Steering gear			NA		
99	---	Forward and backward motion			-		
100	(1), (2) & (3)	Safety glass			IS 2553:2019 (Part 2)		
101	(1) & 2(iii)	Windscreen wiper			IS 15802:2008		
102	(1), (2)	Signaling devices, direction indicators and stop lights			-		
103	(1) & (2)	Position of the indicator			-		
104	1(v) & (4)	Fitment of reflectors & Reflective tapes			AIS-057 (Rev. 1): 2010 & AIS:090-2005		
105	(1)(b), (3),(4), (5) & (7)	Lamps			-		
106	(1)	Deflection of lights			-		
108	(1)	Use of red or white lights			-		
109	---	Parking Lights			-		
110	---	Lamps on 3 Wheelers			AIS-134:2016		
111	-	Prohibition of spotlights etc.			-		
117	(1) & (2)	Speedometer			IS 11827:2008		
119	(1) & (2)	Horns	Installation Limit : 83 dB(A) to 112 dB(A) Observed : 90.9 dB(A)	IS 15796:2008	IS 1884:1993		
120	(2)	Pass by Noise	Performance Limit : 77 dB(A) Observed : 62 dB(A)				
ICAT Ref No.	2023-2302 (IOCS: 174481)						
Power Report No.	CTOPT 0330 dt. 15.04.2024						
Noise Report No.	CTOVT0809 dt. 10.05.2024						
Horn Inst. Report No.	CTOVT0810 dt. 10.05.2024						

AUTHORISED SIGNATORY

JAYWANT HARDIKAR HEAD-CMVR	INSTITUTE FOR AUTOMOTIVE TECHNOLOGY MANESAR * 1950 TO 2050 ICAT Innovation • Service • Excellence	SAURABH DALELA DIRECTOR	Page 2 of 5