



C A T B 0496

Date : 17th May 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard		
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			-		
94	(1), (2), (3)	Condition of tyres			-		
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050-2004		
		Front/ Rear	3.75-12 66B 4PR & 90/90-12, 64B	CEAT			
		Front/ Rear	3.75-12, 60J 4 PR & 90/90-12, 54J	TVS			
			3.75-12 66B 6PR Tube Type/Tubeless	Ralson			
96	(1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999		
99	-	Forward and backward motion			-		
100	(1), (2), (3-A) & (3)(c)	Safety glass as amended by GSR 784(E) – Ref. ANNEXURE - IB			NA		
101	(1)	Windscreen Wiper			NA		
102	(1), (2)	Signaling devices, direction indicators and stop lights			-		
103	(1), (2)	Position of the indicator			-		
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057-2005 & AIS-090-2005		
105	(1)(b), (3), (4), (5), (7)	Lamps			-		
106	(1)	Deflection of lights			-		
108	(1)	Use of red or white lights			-		
109	-	Parking lights			-		
110	-	Lamps for three wheelers			-		
111	-	Prohibition of spotlights etc.			-		
119	(1) & (2)	Horns	Installation		IS 15796:2008		
			Limit :	83 dB(A) to 112 dB(A)			
			Observed :	100.8 dB(A)			
			Performance		IS 1884:1993		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065-2005		
124	-	Safety standards of components as applicable			Refer ANNEXURE - IA & IB		
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-2)Rev.1:2011		
			Installations		AIS-002 (Part-2)Rev.1:2011		

ICAT Ref No.	2023-2159 (IOCS: 174065)
Power Test Report No.	CTOPT 0290 dt. 26.03.2024 & CT0ES 0194 dt. 05.04.2023
Horn Inst. Report No.	CT0VR 0391 dt. 14.03.2022

AUTHORISED SIGNATORY			
			
JAYWANT HARDIKAR HEAD-CMVR		SAURABH DALELA DIRECTOR	Page 2 of 3