



**C A T B 0893**

Date : 26<sup>th</sup> September 2024

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2),(3), (4), (5) & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004
	Front/ Rear	Refer Annexure - IV		
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1), (2), (3-A) & (3)(c)	Safety glass		IS 2553 (Part 2)(Rev 1):2019
101	(1)	Windscreen Wiper		-
102	(1), (2)	Signalling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Horns	Installation	IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)
			Observed :	96.6 dB(A)
		Performance		IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124		Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications Installation	AIS-001 (Part-2)Rev.1:2011
				AIS-002 (Part-2)Rev.1:2011

<b>ICAT Ref No.</b>	2023-2156 (IOCS No. 172671)
<b>Power Test Report No.</b>	CTOPT 0396 dt. 14.05.2024
<b>Horn Inst. Report No.</b>	CT1VT 1328 dt. 27.08.2024

**AUTHORISED SIGNATORY**

JAYWANT HARDIKAR HEAD-CMVR		SAURABH DALELA DIRECTOR	Page 2 of 4