



C	A	S	B	0963	V01
---	---	---	---	------	-----





Date : 05th November 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless - Radial)	Size & ply rating of tyres	Make	IS 15627:2005 & AIS-050:2004	
		Front/Rear			
		145R12LT 86/84E 8PR	Ceat Limited		
		145R12LT 86/84Q 8PR	MRF Ltd		
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	Brakes		IS 14664:2010	
98	(1), (2) & (3)	Steering gear		NA	
99	---	Forward and backward motion		-	
100	(1), (2) & (3)	Safety glass		IS 2553:2019 Part 2(Rev 1)	
101	(1) & 2(iii)	Windscreen wiper		IS 15802:2008	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	1(v) & (4)	Fitment of reflectors & Reflective tapes		AIS-057 (Rev. 1): 2010 & AIS:090-2005	
105	(1)(b), (3), (4), (5) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	---	Parking Lights		-	
110	---	Lamps on 3 Wheelers		AIS-134:2016	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		93 dB(A)
		Performance	IS 1884:1993		
120	(2)	Pass by Noise	Limit :	77 dB(A)	
			Observed :	61 dB(A)	

ICAT Ref No.	2024-0893 (IOCS: 179347)
Power Report No.	CT0ES 0404 dt. 17.08.2023
Noise Report No.	CT1VS 1641 dt. 12.10.2023
Horn Inst. Report No.	ARAI/SHL/CT/APX-2021-25130/0540 dt. 16.02.2021

AUTHORISED SIGNATORY

 JAYWANT HARDIKAR HEAD-CMVR	 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR • 192000	 SAURBH DALELA DIRECTOR	 Page 2 of 4
---	--	--	--