



C A U B 0253

Date : 12th March 2025

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93 94	(1)(A), (1)(B), (2) (1), (2), (3)	Motor vehicle width, length and height Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6)	Size & ply rating of tyres Front/ Rear		IS 15627:2005 & AIS-050-2004
96	(1), (2), (3), (4)(i), (7)(b)	Refer Annexure - IV Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1), (2), (3-A) & (3)(c)	Safety glass		IS 2553 (Part 2)(Rev 1):2019
101	(1)	Windscreen Wiper		-
102	(1), (2)	Signalling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Horns	Installation	IS 15796:2008
			Limit : 83 dB(A) to 112 dB(A)	
			Observed : 100.6 dB(A)	IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications Installation	AIS-001 (Part-1)Rev.1:2011 AIS-002 (Part-1)Rev.1:2011

ICAT Ref No.	2024-1480 (IOCS No. 181954)
Power Test Report No.	CT0ER 0499 dt. 08.12.2022 & CT0PU 0238 dt. 25.02.2025
Horn Inst. Report No.	CT0VU 0256 dt. 05.02.2025

AUTHORISED SIGNATORY		 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY MANESAR Innovation • Service • Excellence
JAYWANT HARDIKAR HEAD-CMVR		
SAURABH DALELA DIRECTOR		 Innovation • Service • Excellence