



C A U B 0345

Date : 28th March 2025

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-
94	(1), (2) & (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6) (Tubeless/Tube Type - Cross Ply)	Size & ply rating of tyres	Make	IS 15627:2005 & AIS-050:2004
		Front/Rear	4.50-10 85E 8PR M/s MRF(Tube) M/s ZAHN TYRES(Tubeless)	
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	Brakes		IS 14664:2010
98	(1), (2) & (3)	Steering gear		NA
99	---	Forward and backward motion		-
100	(1), (2) & (3)	Safety glass		IS 2553:2019 Part 2(Rev 1)
101	(1) & 2(iii)	Windscreen wiper		IS 15802:2008
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1) & (2)	Position of the indicator		-
104	1(v) & (4)	Fitment of reflectors & Reflective tapes		AIS-057 (Rev. 1): 2010 & AIS:090-2005
105	(1)(b), (3), (4), (5) & (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	---	Parking Lights		-
110	---	Lamps on 3 Wheelers		AIS-134:2016
111	-	Prohibition of spotlights etc.		-
117	(1) & (2)	Speedometer		IS 11827:2008
119	(1) & (2)	Horns	Installation	IS 15796:2008
			Limit : 83 dB(A) to 112 dB(A)	
			Observed : 94.8 dB(A)	
120	(2)	Pass by Noise	Performance	IS 1884:1993
			Limit : 77 dB(A)	IS 3028:1998
			Observed : 65 dB(A)	

ICAT Ref No.	2024-1585 (IOCS: 180070)
Power Report No.	CT0PU 0317 dt. 18.03.2025
Noise Report No.	CT0VU 0576 dt. 28.03.2025
Horn Inst. Report No.	CT0VU 0577 dt. 28.03.2025

AUTHORISED SIGNATORY

 JAYWANT HARDIKAR HEAD-CMVR		 SAURABH DALELA DIRECTOR	 Page 2 of 4
--	---	--	--