

## NATIONAL AUTOMOTIVE BOARD (NAB)]

TAC/Reference No. C S 0 2 3 7

Date : 26th Feb 2025

CS0237

Cert	© Dwgs	Total
1 Ms.	4 🔊	05 pgs

## TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037)

Non- Transferable

MA 1	Customer's Name	M/s. JMC WORKS PVT. LTD.,	MOEK SAL	
2	Customer's Address	A-187 MIA Alwar, Rajasthan	is who were chose	
<b>3</b> 500	Manufacturing / Assembly Plant Address	Same as mentioned in Sc. No. 1 & 2 above.		
Strait	Ely. "Han Dikita, "Is"	Component Name	Metallic Fuel Tank (Diesel)	
NO	ESS M	Vehicle Manufacturer	M/s Ashok Leyland Ltd.	
Me. Inc	" White Office I was to see that the see of	Part No. Hard No.	MB411081	
4	Description of the Test Component(s)	Application on Vehicle Model	Passenger / Goods Model of	
P.M.	Esolai sinit choth	Thickness(mm)	MS 1.6 AME	
X <sub>2</sub>	legitar ID. P. M. July direct the	Capacity (liters)	350 NA	
Alwar P	8" LE 8111." ES0131 181 MA	Material West	DX 52D + AS as per BS EN10340	
5 min	Applicable Notified Standard	AIS-095:2007 with its Amendment No. 1, May 2014		
7,31 1	Test Report No.	CT0CU0236 dated 24.02.2025	S. Int. C. Brings Falls	
8	List of supporting documents	Drawing Nos. Sheet 1 of 2 & Sheet 2 of M41101062#	f 2 of MB411081 #, FHT00190 A &	
8.1	Pre-test inspection Visit Report No.	CT0CF0302 dated 02.03:2010	CEP131	
9 AT	Details of Quality Management System (QMS)	ISO 9001:2015, Certificate No. 3050230	71829Q, valid until 02.06.2026	
10	Approval	Granted/ Not	X X Granted/Extended	
11 cs	The CoP period for the component mentioned shall be completed before 30.09.2026.	d in Sr. No. 4 above shall begin from the	e date of production & 1st Cop	

10.	1/2		C. *	C	
	ICAT Reference	© CCTNJMCW PAC	TL183398	Please turn over for DISCL	AIMER
	AUTHORISED SIGNATORY	kijos v	el me	ing the	S
	ACS LANGERS BALL THE BASE SHAPE CERTS IN S. S. L.	'se, and base, the Moste by	Innovation - Service - Excellence	State	Ingyguion s Service e Excelence
٥.	HARISH JOSHI	PRITAM SINGH SAWARIYA	* MANUTON B * 13	CS023726thFeb2 <b>SAURABH</b> DAWE CS023726thF	Page 1 of
	Manager <sup>©</sup>	Senior Manager	MANESAN	Director ICAT	65°1