Corrigendum No. CTOYTO277

CT0XT 0277

CORRIGENDUM -1

Non- Transferable

	Light skills the same of the s	M/s. Jiangsu Hankook Tire Co. Ltd.,	
,	Manufacturer's Name & Address	1# South Hantai Road, Huaian EDZ, Huaian City, 223001, Jiangsu	
	The state of the s	Province, China.	
38,	Manufacturing/Assembly Plant Address	Same as mentioned above	

This corrigendum is issued for the following Type Approval Certificate(s) (TACs) issued: -

N	_ ~~				
# _{Hartial}	Reference/TAC No. & Date	.≪Ref. Page	Parameter	Earlier issued TAC No.	Corrected TAC No.
* ⁵ 1	YN0088, dt. 08.03.2022	- ROO	TAC No.	YN0088	CN0088
2	YN0087, dt. 08.03.2022	Jill Hai		YN0087	CN0087
3	YM0318, dt. 16.09.2021	- 1/1/2°		YM0318	CM0318
< ²⁰ 4	YM0319, dt. 16.09.2021	, DI.		YM0319	CM0319
5 Hudian	YM0109, dt. 25.03.2021	Higita -		YM0109	CM0109
€6	YM0108, dt. 25.03.2021	- 2230		YM0108	CM0108

Reason for corrigendum:

Type Approval Certificate numbers were issued inadvertently with the first letter as "Y" instead of "C".

This corrigendum is being issued to address the same and new TAC/Corrected TAC nos. are being issued.

Note:

- This corrigendum to be used in conjunction to the earlier TACs issued (as mentioned above) and subsequent COPs.
- These changes will be regularized in upcoming & running cases of COP and TACs.

