







C A U B 0074

Date : 23th January 2025

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004	
		Front/Rear	Make		
96	(1), (2), (3), (4)(i), (7)(b)	Refer Annexure - IV		IS 14664:1999	
99	-	Brakes		-	
100	(1), (2), (3-A) & (3)(c)	Forward and backward motion		-	
101	(1)	Safety glass		IS 2553 (Part 2)(Rev 1):2019	
102	(1)	Windscreen Wiper		-	
103	(1), (2)	Signaling devices, direction indicators and stop lights		-	
104	(1), (2)	Position of the indicator		-	
105	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005	
106	(1)(b), (3), (4), (5), (7)	Lamps		-	
108	(1)	Deflection of lights		-	
109	(1)	Use of red or white lights		-	
110	-	Parking lights		-	
111	-	Lamps for three wheelers		-	
112	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		94.1 dB(A)
120	(1) & (2)	Performance		IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part-2)Rev.1:2011	
		Mirror	Installation	AIS-002 (Part-2)Rev.1:2011	

ICAT Ref No.	2024-1097 (IOCS No. 180290)
Power Test Report No.	CT0ET 0069 dt. 23.02.2024 & CT0PT-0822 dt. 06.12.2024
Horn Inst. Report No.	CT0VT 1961 dt. 18.12.2024

AUTHORISED SIGNATORY				
	JAYWANT HARDIKAR HEAD-CMVR			