



C	A	P	N	0004	F01
---	---	---	---	------	-----


Date : 06<sup>th</sup> February 2025

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2) & (3)	Motor vehicles width, length & height		-
94	(1), (2) & (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6) (Radial Ply and Cross Ply with tube)	<b>Size &amp; ply rating of tyres</b>		IS-15636-2012, AIS-051:2004
		<b>Make</b>		
		Front	7.50 R16-16PR 8.25 R16-16PR 7.50 X16-16PR 8.25 X16-16PR	
	Rear			
	(1A)	Rolling Resistance, Wet Grip & Rolling Sound Emission		AIS 142:2019
96	(1), (2), (3), (4)(ii) & (8)	Brakes with ABS		IS 11852 : 2013
98	(1), (2), (3) & (4)	Steering Gear		IS-12222:2011
		Steering Effort		IS-11948:2010
99	-	Forward and backward motion		-
100	(1), (2), (3) & (3)(C)	Safety glass		IS 2553 (Part 2) (Revision 1): 2019
101	(1) & (2)(ii)	Windscreen wiper		IS 15802:2008
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-
103	(1) & (2)	Position of the indicator		-
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010, AIS 90:2019
105	(1)(a), (2), (3), (4), (5)& (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking light		-
111	-	Prohibition of spotlights etc.		-
114	(1) & (2)	Exhaust gases and exhaust pipes		-
115	(1), (2)(ii) & (18)(ii)	Emission of smole, vapour, etc. from motor vehicle (including QBD II)		AIS 137 Part 4
117	(1) & (2)	Speedometer		IS-11827:2008
118	(1) & (2)	Speed Governor (ECU- M/s. Bosch India Ltd., ID- 0281020754)		AIS: 018- 2001
<b>ICAT Ref No.</b>		2024 -1911 (IOCS Ref: 183270)		
<b>Net Power Test Report No.</b>		CT0ER 0424 dt. 02.11.2022, CT0ER 0424 E01 dt. 18.06.2023 & CT0ER 0425 dt. 02.11.2022 (OBD II)		
<b>Pass By Noise Report No.</b>		CT0VT 1369 dt. 03.09.2024		
<b>Horn Inst. Report No.</b>		CT0VL 0675 dt. 25.10.2016 & CT0VU 0221 dt. 30.01.2025		

**AUTHORISED SIGNATORY**






**JAYWANT HARDIKAR**  
HEAD-CMVR

**SAURABH DALELA**  
DIRECTOR