

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B) & (2)	Motor Vehicle width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front	90/90-12		1. TVS 2. (MAXXIS) CHENG SHIN
		Rear	110/90-10		
96	(1), (2), (3), (4)(ib), (4A), (7)(c) & (8)	Brakes with ABS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
114	(1) & (2)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(i) & (19)(i)	Emission of smoke, vapour, etc. from motor vehicle		AIS-137	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Above 7kW)		IS 15796:2008
			Limit :	87 dB(A) to 112 dB(A)	
			Observed :	96.5dB(A) / 100.2dB(A)	
			Performance		IS 1884:1993
120	(1)	Silencers		-	
	(2)	Pass by Noise	Limit :	77 dB(A) (80 < cc ≤ 175)	IS 3028:1998
			Observed :	69.9dB(A)	
122	(1) & (2)	Embossment of chassis number & engine number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Pillion Hand Hold		IS 14495:1998	
	(2)	Footrest		AIS 148:2018	
	(4)	Stand		AIS 146:2018	
	(5)	External projection		AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part 2) (Rev.1):2011
			Installation		AIS-002 (Part 2) (Rev.1):2011

<b>ICAT Ref No.</b>	2024 - 1251; IOCS Ref:- 180256
<b>Emission Report No.</b>	CT0PS 0230 dt. 11.01.2023, CT0PT 0738 dt. 29.10.2024
<b>Noise Report No.</b>	CT0VR 1776 dt. 19.12.2022
<b>Horn Inst. Report No.</b>	CT0VO 0785 dt. 14.08.2019
<b>FTP Report No.</b>	CT0ER 0312 dt. 29.07.2022

<b>AUTHORISED SIGNATORY</b>		
<b>JAYWANT HARDIKAR HEAD-CMVR</b>	<b>SAURABH DALELA DIRECTOR</b>	Page 2 of 4