

| | | | | | |
|---|---|---|---|------|-----|
| C | A | K | B | 0095 | F01 |
|---|---|---|---|------|-----|

Date : 15th January 2025

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard | |
|----------|-------------------------------|--|----------------|------------------------------|-----------------------|
| 93 | (1)(A), (1)(B), (2) | Motor vehicle width, length and height | | - | |
| 94 | (1), (2), (3) | Condition of tyres | | - | |
| 95 | (1), (2),(3), (4), (5) & (6) | Size & ply rating of tyres | | IS 15627:2005 & AIS-050-2004 | |
| | | Front/ Rear | Make | | |
| 96 | (1), (2), (3), (4)(i), (7)(b) | Refer Annexure - IV | | IS 14664:1999 | |
| 99 | - | Brakes | | - | |
| 100 | (1), (2), (3-A) & (3)(c) | Forward and backward motion | | - | |
| 101 | (1) | Safety glass | | - | |
| 102 | (1), (2) | Windscreen Wiper | | - | |
| 103 | (1), (2) | Signaling devices, direction indicators and stop lights | | - | |
| 104 | (1)(v),(4) | Position of the indicator | | - | |
| 105 | (1)(b), (3), (4), (5), (7) | Fitment of reflectors & reflective tapes | | AIS-057-2005 & AIS-090-2005 | |
| 106 | (1) | Lamps | | - | |
| 108 | (1) | Deflection of lights | | - | |
| 109 | - | Use of red or white lights | | - | |
| 110 | - | Parking lights | | - | |
| 111 | - | Lamps for three wheelers | | - | |
| 119 | (1) & (2) | Horns | Installation | IS 15796:2008 | |
| | | | Limit : | | 83 dB(A) to 112 dB(A) |
| | | | Observed : | | 93.8 dB(A) |
| | | | Performance | | IS 1884:1993 |
| 122 | (1) & (2) | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) | | AIS-065-2005 | |
| 124 | - | Safety standards of components as applicable | | Refer ANNEXURE - IA & IB | |
| 125 | (2)(a) | Rear View Mirror | Specifications | AIS-001 (Part-2)Rev.1:2011 | |
| | | | Installation | AIS-002 (Part-2)Rev.1:2011 | |

| | |
|-----------------------|-----------------------------|
| ICAT Ref No. | 2024-0762 (IOCS No. 178520) |
| Power Test Report No. | CT0PK 0254 dt. 26.06.2015 |
| Horn Inst. Report No. | CT0CK 1349 dt. 19.07.2015 |

| | | | |
|--------------------------------------|--|-----------------------------------|----------------|
| AUTHORISED SIGNATORY | | | |
| | | | |
| JAYWANT HARDIKAR HEAD-CMVR | | SAURABH DALELA DIRECTOR | Page 2 of 4 |