



C A R N 0952

Date : 15th September 2022

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1A), (1B), (2) & (3)	Motor Vehicle width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2),(3), (4), (5), (6) & (7) (Tubeless, Radial & Run-Flat)	Size & ply rating of tyres		IS-15633:2005, AIS-051:2004	
		Front	235/55 R18 100 V		Continental
		Rear			
		Temporary Use Spare Wheel	T125 70 R18 100 M	Zhongce	AIS-110:2009
	(8)	Tyre pressure monitoring system		AIS 154 : 2018	
96	(1), (2), (3), (4)(ii), (4B), (7)(a) & (8)	Brakes		IS-15986:2015	
	(10)	Electronic Stability Control		AIS 133:2016	
	(11)	Brake assist System		AIS 152:2018	
96B	(a) & (b)	High Speed Brake Requirements		IS-15986:2015	
98	(3)	Steering gear		IS-11948:2010	
	(1), (2)			IS-12222:2011	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (3c)	Safety glass		IS 2553 (Part 2)(Rev.1) :2019	
101	(1) & (2)	Windscreen wiper		IS-15804:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1) (a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
112	-	Exhaust gases		-	
113	-	Location of exhaust pipes		-	
115	(1), (2)(i), 18(i)	Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (Including OBD I & OBD II))		AIS-137	
115G	(1) & (2)	Fuel Consumption Standard		-	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1)	Speed Governor		NA	

ICAT Ref No.	2022 - 0942 [IOCS No.: 159025]		
Emission Report No.	CT0PR 1025 DT. 13.09.2022		
Noise Report No.	CT0VR 1244 dt. 09.09.2022		
Horn Inst. Report No.	CT0VN 0515 dt. 23.03.2018	FTP Report No.	CT0ER 0333 DT. 17.08.2022

AUTHORISED SIGNATORY			
			
			