




C A R N 0954

Date : 16th September 2022

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard |
|----------|---|--|-------------------------------|---|
| 93 | (1)(A), (1)(B), (2) & (3) | Motor Vehicle width, length and height | | - |
| 94 | (1), (2) & (3) | Condition of tyres | | - |
| 95 | (1), (2), (3), (4), (5), (6) & (7) (Tubeless & Radial) | Size & ply rating of tyres | Make |  IS-15633:2005, AIS-051:2004 AIS-142:2019 |
| | | Front / Rear / Spare | 155R13C 8PR 90/89S JK Tyre | |
| | (8) | Tyre pressure monitoring system | | NA |
| 96 | (1), (2), (3), (4)(ii), (4B), (7)(a) & (8) | Brakes | | IS-15986:2015 |
| | (10) | Electronic Stability Control | | AIS-133:2016 |
| | (11) | Brake Assist System | | AIS-152:2018 |
| 96B | (a) & (b) | High Speed Brake Requirements | | IS-15986:2015 |
| 98 | (3) | Steering gear | | IS-11948:2010 |
| | (1), (2) | | | IS-12222:2011 |
| 99 | - | Forward and backward motion | | - |
| 100 | (1), (2), (3) & (3c) | Safety glass | | IS 2553 (Part 2)(Rev.1) :2019 |
| 101 | (1) & (2) | Windscreen wiper | | IS-15804:2008 |
| 102 | (1) & (2) | Signalling devices, direction indicators and stop lights | | - |
| 103 | (1) & (2) | Position of the indicator | | - |
| 104 | (1) & (4) | Fitment of reflectors | | AIS-057 (Rev. 1): 2010 |
| 105 | (1) (a), (2), (3), (4) & (7) | Lamps | | - |
| 106 | (1) | Deflection of lights | | - |
| 108 | (1) | Use of red or white lights | | - |
| 109 | - | Parking light | | - |
| 111 | - | Prohibition of spotlights etc. | | - |
| 114 | (1) & (2) | Exhaust gases and exhaust pipes | | - |
| 115 | (1), (2)(i), 18(i) | Emission of smoke, vapour, etc. from motor vehicle | | AIS-137 |
| 115G | (1) & (2) | Fuel Consumption Standard | | AIS-137 |
| 117 | (1) & (2) | Speedometer | | IS-11827:2008 |
| 118 | (1) | Speed Governor - SLF in ECU (Only for Tour Variants) | | AIS-018:2001 |

| | |
|-----------------------|---------------------------|
| ICAT Ref No. | 2022-0654[IOCS No.158852] |
| Emission Report No. | CT0PR 1019 dt. 12.09.2022 |
| Noise Report No. | CT0VR 1206 dt. 05.09.2022 |
| FTP Report No. | CT0ER 0364 dt. 12.09.2022 |
| Horn Inst. Report No. | CT0VR 1172 dt. 25.08.2022 |

| | | | | |
|---|---|---|---|---|
| AUTHORISED SIGNATORY | |  |  Pamela Tikku |  |
| <small>AIS-142-2019Spare155R13C8PR90/89SJKTyre96B(a)&(b)HighS98(3)AIS-142-2019Spare155R13C8PR90/89SJKTyre96B(a)&(b)HighS98(3)</small> | <small>AIS-142-2019Spare155R13C8PR90/89SJKTyre96B(a)&(b)HighS98(3)AIS-142-2019Spare155R13C8PR90/89SJKTyre96B(a)&(b)HighS98(3)</small> | | | |