



C A R N 0912

Date : 02nd September 2022

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2) & (3)	Motor Vehicle width, length and height		-
94	(1), (2) & (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5), (6) & (7) (Tubeless & Radial)	Size & ply rating of tyres	Make	IS-15633:2005, AIS-051:2004 AIS-142:2019
		Front / Rear / Spare	155R13C 8PR 90/89S JK Tyre	
	(8)	Tyre pressure monitoring system		NA
96	(1), (2), (3), (4)(ii), (4B), (7)(a) & (8)	Brakes		IS-15986:2015
	(10)	Electronic Stability Control		AIS-133:2016
	(11)	Brake Assist System		AIS-152:2018
96B	(a) & (b)	High Speed Brake Requirements		NA
98	(3)	Steering gear		IS-11948:2010
	(1), (2)			IS-12222:2011
99	-	Forward and backward motion		-
100	(1), (2), (3) & (3c)	Safety glass		IS 2553 (Part 2)(Rev.1) :2019
101	(1) & (2)	Windscreen wiper		IS-15804:2008
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-
103	(1) & (2)	Position of the indicator		-
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010
105	(1) (a), (2), (3), (4) & (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking light		-
111	-	Prohibition of spotlights etc.		-
114	(1) & (2)	Exhaust gases and exhaust pipes		-
115	(1), (2)(i), 18(i)	Emission of smoke, vapour, etc. from motor vehicle		AIS-137
115G	(1) & (2)	Fuel Consumption Standard		AIS-137
117	(1) & (2)	Speedometer		IS-11827:2008
118	(1)	Speed Governor - SLF in ECU (Only for Tour Variants)		AIS-018:2001

ICAT Ref No.	2022-0654[IOCS No.158853]
Emission Report No.	CT0PR 1017 dt. 12.09.2022
Noise Report No.	CT0VR 1206 dt. 05.09.2022
FTP Report No.	CT0ER 0364 dt. 12.09.2022
Horn Inst. Report No.	CT0VR 1172 dt. 25.08.2022

**AUTHORISED SIGNATORY**

	 <b>PAMELA TIKKU</b> <b>DIRECTOR (Offg.)</b>	 <b>VIJAYANTA AHUJA</b> <b>DEPUTY GENERAL MANAGER</b>	 <b>Manesar</b>
---	---	--	---