



**C A R B 1003**

Date : 06<sup>th</sup> October 2022

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-
94	(1), (2) & (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004
		Front	100/80-12 56L	
		Rear	110/80-12 61L	JK Tyre (Cavendish)
96	(1), (2), (3), (4)(ib), 4-A (7)(c) & (8)	Brakes with CBS		IS 14664:2010
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-
103	(1)	Position of the indicator		-
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010
105	(1)(bb), (2)(i) & (4)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
111	-	Prohibition of spotlights etc.		-
117	(1) & (2)	Speedometer		IS 11827:2008
119	(1) & (2)	Horns	Installation (Below 7kW)	IS 15796:2008
			Limit : 83 dB(A) to 112 dB(A)	
			Observed : 83 dB(A)	
			Performance	IS 1884:1993
120	(2)	Pass by Noise	Limit : 75 dB(A)	IS 3028:1998
			Observed 63 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005
123	(1), (2), (4), (5)	Safety devices in motor cycle	Pillion Handhold	IS 14495-1998
			Footrests	AIS 148:2018
			Stand	AIS 146:2018
			External Projection	AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-
125	(2)(a)	Rear View	Specifications	AIS-001 (Part 2) (Rev.1):2011
		Mirror	Installation	AIS-002 (Part 2) (Rev.1):2011

<b>ICAT Ref No.</b>	2022-0451 (IOCS Ref: 158764)
<b>Power Test Report No.</b>	CTOER 0152 dt. 26.03.2022
<b>Noise Report No.</b>	CTOVR 1225 dt 07.09.2022
<b>Horn Inst. Report No.</b>	CTOVR 1226 dt 07.09.2022

<b>AUTHORISED SIGNATORY</b>				
<b>VIJAYANTA AHUJA</b> <b>DEPUTY GENERAL MANAGER</b>	<b>PAMELA TIKKU</b> <b>DIRECTOR (Offg.)</b>			