



C A O N 0301 V02

Date : 14th November 2022

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B) & (2)	Motor Vehicle width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless) (Fr. - Cross Ply) (Rr.- Radial)	Front	100/80-17M/C 52P	IS 15627:2005 & AIS-050:2004	
		Rear	140/60R17M/C 63P		
96	(1), (2), (3), (4(ib)), (4A), (7)(c) & (8)	Brakes with ABS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
114	(1) & (2)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(i) & (19)(i)	Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (Including OBD I))		AIS-137	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Above 7kW)	IS 15796:2008	
			Limit :		87 dB(A) to 112 dB(A)
			Observed :		94.3 dB(A)
			Performance	IS 1884:1993	
120	(1)	Silencers		-	
	(2)	Pass by Noise	Limit : 77 dB(A) (80 < cc ≤ 175 cc) Observed : 68.4 dB(A)	IS 3028:1998	
122	(1) & (2)	Embossment of chassis number & engine number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Pillion Hand Hold		IS 14495:1998	
	(2)	Footrest		AIS 148:2018	
	(4)	Stand		AIS 146:2018	
	(5)	External projection		AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part 2) (Rev.1):2011	
			Installation	AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2022-1428 (IOCS: 162308)
Emission Report No.	CT0PO 1088 dt. 05.12.2019
Noise Report No.	CT1VO 0941 dt. 18.09.2019
Horn Inst. Report No.	CT0VO 0292 dt. 27.02.2019
FTP Report No.	CT0EO 0383 dt. 23.11.2019

AUTHORISED SIGNATORY

--	--	--