



C A S N

Date : 06<sup>th</sup> January 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B) & (2)	Motor Vehicle width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front	100/80-17M/C 52P		MRF
		Rear	140/70R17M/C 66H		
96	(1), (2), (3), (4)(ib), (4)(A), (7)(c) & (8)	Brakes with ABS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
114	(1) & (2)	Exhaust gases and exhaust pipes		-	
115	(1),(2)(i) & (19) (i)	Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (Including OBD II))		AIS 137	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Above 7kW)	IS 15796:2008	
			Limit :		87 dB(A) to 112 dB(A)
			Observed :		91.2 dB(A)
			Performance	IS 1884:1993	
120	(1) (2)	Pass by Noise	Limit :	IS 3028:1998	
			Observed :		77 dB(A) (80 < cc ≤ 175)
					72.2 dB(A)
122	(1) & (2)	Embossment of chassis number & engine number & month of manufacture (Ref. Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)(a)	Safety devices in motor cycle (Pillion Hand Hold)		IS 14495:1998	
123	(2)	Safety devices in motor cycle (Footrest)		AIS 148:2018	
123	(4)	Safety devices in motor cycle (Stand)		AIS 146:2018	
123	(5)	Safety devices in motor cycle (External Projection)		AIS 147:2018	

ICAT Ref No.	2022-0886 (IOCS No. :160048)
Emission Report No.	CT0PS0208 Dt: 03.01.2023
FTP Report No	CT0ER 0502 dt. 09.12.2022
Noise Report No.	CT0VR 1818 dt. 27.12.2022
Horn Inst. Report No.	CT0VQ 0641 dt. 17.06.2021

<b>AUTHORISED SIGNATORY</b>			
<b>MADHUSUDAN JOSHI</b> DEPUTY GENERAL MANAGER	<b>SAURABH DALELA</b> DIRECTOR		