



C A R B 0688 F01

Date : 20<sup>th</sup> February 2023

## **ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), 1(B), 2	Motor vehicle width, length and height			-
94	(1), (2) & (3)	Condition of tyres			-
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050:2004
	Front/ Rear	90/90-14, 46P		M/s. TVS	
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes with CBS			IS 14664:2010
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights			-
103	(1)	Position of the indicator			-
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010
105	(1)(bb), (2)(i) & (4)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
111	-	Prohibition of spotlights etc.			-
117	(1) & (2)	Speedometer			IS 11827:2008
119	(1) & (2)	Horns	Installation (Below 7kW)		IS 15796:2008
			Limit :	87 dB(A) to 112 dB(A)	
			Observed :	90.7 dB(A)	IS 1884:1993
			Performance		
120	(2)	Pass by Noise	Limit :	75 dB(A)	IS 3028:1998
			Observed :	57 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005
123	(1) (2) (4) (5)	Safety devices in motor cycle		Pillion Handhold	IS 14495:1998
				Footrests	AIS 148:2018
				Stand	AIS 146:2018
				External Projection	AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part 2) (Rev.1):2011
			Installation		AIS-002 (Part 2) (Rev.1):2011

<b>ICAT Ref No.</b>	2022-1909 (IOCS Ref: 164441)
<b>Power Test Report No.</b>	CT0PS 0228 dt. 11.01.2023
<b>Noise Report No.</b>	CT1VS 0179 dt. 02.02.2023
<b>Horn Inst. Report No.</b>	CT0VS 0125 dt. 27.01.2023

**AUTHORISED SIGNATORY**

**MADHUSUDAN JOSHI**  
**DEPUTY GENERAL MANAGER**



**SAURABH DALELA**  
**DIRECTOR**

