



C A S B 0292

Date : 16th March 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), 1(B), 2	Motor vehicle width, length and height			-
94	(1), (2) & (3)	Condition of tyres			-
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Front/ Rear	Size & ply rating of tyres 90/100-10, 53J 4PR	Make RALSON / CEAT / TVS	IS 15627:2005 & AIS-050:2004
96	(1), (2), (3), (4)(b), (7)(c) & (8)	Brakes with CBS			IS 14664:2010
102	(1), (2) & (3)	Signalling devices, direction indicators and stop lights			-
103	(1)	Position of the indicator			-
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010
105	(1)(bb), (2)(i) & (4)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
111	-	Prohibition of spotlights etc.			-
117	(1) & (2)	Speedometer			IS 11827:2008
119	(1) & (2)	Horns	Installation (Below 7kW) Limit : 83 dB(A) to 112 dB(A) Observed : 90.2 dB(A)	Performance	IS 15796:2008 IS 1884:1993
120	(2)	Pass by Noise	Limit : 75 dB(A) Observed : 62 dB(A)		IS 3028:1998
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005
123	(1)	Safety devices in motor cycle		Pillion Handhold	IS 14495:1998
	(2)			Footrests	AIS 148:2018
	(4)			Stand	AIS 146:2018
	(5)			External Projection	AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-
125	(2)(a)	Rear View Mirror	Specifications Installation		AIS-001 (Part 2) (Rev.1):2011 AIS-002 (Part 2) (Rev.1):2011

ICAT Ref No.	2022-1624 (IOCS Ref: 163121)
Power Test Report No.	CTOPR 0933 dt. 29.07.2022
Noise Report No.	CTOVS 0387 dt. 06.03.2023
Horn Inst. Report No.	CTOVS 0392 dt. 06.03.2023

AUTHORISED SIGNATORY

MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR	SAURABH DALELA DIRECTOR	 Page 2 of 4
--	---	----------------------------	--