



**C A R B 0078 F01**

**Date : 25<sup>th</sup> March 2023**

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front/Rear	90/90-12, 54L		M/s RALCO
			90/90-12, 54J		M/s CEAT
90/90-12, 54L	M/s BRAZA				
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes with CBS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Below 7kW)	IS 15796:2008	
			Limit : 83 dB(A) to 112 dB(A)		
			Observed : 86.2 dB(A)		
			Performance		IS 1884:1993
120	(2)	Pass by Noise	Limit : 75 dB(A)	IS 3028:1998	
			Observed 58 dB(A)		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1), (2), (4), (5)	Safety devices in motor cycle	Pillion Handhold	IS 14495:1998	
			Footrests	AIS 148:2018	
			Stand	AIS 146:2018	
			External Projection	AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation	AIS-002 (Part 2) (Rev.1):2011	

<b>ICAT Ref No.</b>	2022-2086 (IOCS Ref: 164655)
<b>Power Test Report No.</b>	CTOPS 0472 dt. 24.03.2023
<b>Noise Report No.</b>	CT0VQ 1515 dt. 21.12.2021
<b>Horn Inst. Report No.</b>	CT0VQ 1516 dt. 21.12.2021

<b>AUTHORISED SIGNATORY</b>			
<b>MADHUSUDAN JOSHI</b> <b>DEPUTY GENERAL MANAGER</b>	<b>SAURABH DALELA</b> <b>DIRECTOR</b>		