



C A S B 0355

Date : 27th March 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front/Rear	Make		
		90/90-12, 54L	RALCO		
		90/90-12, 54L	RALCO		
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Installation (Below 7kW)		IS 15796:2008	
		Limit :	83 dB(A) to 112 dB(A)		
		Observed :	89.8 dB(A)		
		Performance		IS 1884:1993	
120	(2)	Pass by Noise	Limit :	75 dB(A)	IS 3028:1998
			Observed	58 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle	Pillion Handhold		IS 14495:1998
	(2)		Footrests		AIS 148:2018
	(4)		Stand		AIS 146:2018
	(5)		External Projection		AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications		AIS-001 (Part 2) (Rev.1):2011
		Mirror	Installation		AIS-002 (Part 2) (Rev.1):2011

ICAT Ref No.	2022-1202 (IOCS Ref: 161279)
Power Test Report No.	CTOES 0158 dt. 21.03.2023
Noise Report No.	CTOVS 0483 dt 17.03.2023
Horn Inst. Report No.	CTOVS 0488 dt 17.03.2023

AUTHORISED SIGNATORY			
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR		