



C	A	S	B	0526	F01
---	---	---	---	------	-----

Date : 29th May 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2),(3),(4),(5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004
		Front	90/90-12 54J	TVS
			3.75x12 66E	Apollo, JK Tyre
			90/90-12 64B	JK Tyre, CEAT, Apollo
		Rear	90/90-12 54L, 3.00x12 63B	RALSON
			3.75x12 66B	Ralson, CEAT, Poddar
			3.75x12 60J	TVS
			4.50x12 77/76J	Ralson
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1),(2),(3)	Safety glass		IS 2553(Part 2)(Rev.1):2019
101	(1),(2)	Windscreen Wiper		IS 15802-2008
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS-090-2005
105	(1)(b),(3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Horns	Installation	IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)
			Observed :	88.9 dB(A)
		Performance		IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-2)Rev.1:2011
			Installation	AIS-002 (Part-2)Rev.1:2011

ICAT Ref No.	2022-1911;(IOCS :164364)
Power Test Report No.	CTOPS 0554 Dt.30.03.2023
Horn Inst. Report No.	CTOVS 0660 Dt.13.04.2023

AUTORISED SIGNATORY				
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER				
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR			Page 2 of 3