



C	A	Q	B	1108	F01
---	---	---	---	------	-----

Date : 08th June 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), 1(B), 2	Motor vehicle width, length and height			-
94	(1), (2) & (3)	Condition of tyres			-
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050:2004
		Front/ Rear	90/90-12 54J	M/s. TVS	
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes with CBS			IS 14664:2010
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights			-
103	(1)	Position of the indicator			-
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010
105	(1)(bb), (2)(i) & (4)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
111	-	Prohibition of spotlights etc.			-
117	(1) & (2)	Speedometer			IS 11827:2008
119	(1) & (2)	Horns	Installation (Below 7kW)		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	86.5 dB(A)	
Performance			IS 1884:1993		
120	(2)	Pass by Noise	Limit :	75 dB(A)	IS 3028:1998
			Observed	63 / 61 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005
123	(1)	Safety devices in motor cycle	Pillion Handhold		IS 14495:1998
	(2)		Footrests		AIS 148:2018
	(4)		Stand		AIS 146:2018
	(5)		External Projection		AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part 2) (Rev.1):2011
			Installation		AIS-002 (Part 2) (Rev.1):2011

ICAT Ref No.	2023-0185 (IOCS Ref: 166901)
Power Test Report No.	CT0PO 0928 dt: 31.07.2019, CT0ES 0283 dt. 31.05.2023, CT0ES 0283 dt. 31.05.2023
Noise Report No.	CTOVO 0761 dt. 09.08.2019, CT1VS 0932 dt. 06.06.2023
Horn Inst. Report No.	CTOVO 0761 dt. 09.08.2019

AUTORISED SIGNATORY		
 MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	 SAURABH DALELA DIRECTOR	Page 2 of 4