





C	A	Q	B	1108	F01
---	---	---	---	------	-----

Date : 08th June 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front/ Rear	90/90-12 54J		M/s. TVS
96	(1), (2), (3), (4)(ib), (4)(A), (7)(c) & (8)	Brakes with CBS		IS-14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Below 7kW)		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	86.5 dB(A)	
120	(2)	Pass by Noise	Performance		IS 1884:1993
			Limit :	75 dB(A)	
122	(1) & (2)		Observed		IS 3028:1998
			63 / 61 dB(A)		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle	Pillion Handhold		IS 14495:1998
	(2)		Footrests		AIS 148:2018
	(4)		Stand		AIS 146:2018
	(5)		External Projection		AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications		AIS-001 (Part 2) (Rev.1):2011
		Mirror	Installation		AIS-002 (Part 2) (Rev.1):2011

ICAT Ref No.	2023-0185 (IOCS Ref: 166901)
Power Test Report No.	CTOES 0283 dt. 31.05.2023, CTOES 0284 dt. 31.05.2023
Noise Report No.	CTOVO 0761 dt. 09.08.2019, CT1VS-0932 dt. 06.06.2023
Horn Inst. Report No.	CTOVO 0761 dt. 09.08.2019

AUTHORISED SIGNATORY			
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR		