





C A P A 0069 V06

ANNEXURE - I

Date : 29th June 2023

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1), (2), (4), (6) & (7)	Overall dimension of motor vehicles		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2),(3), (4), (5), (6) (Cross Ply / with Tube)	Size & ply rating of tyres		IS-15636-2005 & AIS:051: 2004	
		Front	8.25" X16"-16 PR (single)		M/s. CEAT/Apollo/JK Ind
		Rear	8.25" X16"-16 PR (dual)		
96	(1), (2), (3), (4)(ii), (7)(a), (8)	Brakes with ABS		IS-11852:2013	
98	(1), (2), (3)	Steering Gear		IS-11948:2010	
		Turning Circle Diameter		IS-12222:2011	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (4)	Safety glass		IS 2553 (Part 2) (Revision 1): 2019	
101	(1) & (2)(ii)	Windscreen wiper		IS 15802:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1), (2), (4) & (5)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1) (a), (2), (3), (4), (5) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
114	(1), (2)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(ii), (15) (a),(b) (ii), (A)	Emission of smoke, vapour, etc. from motor vehicle (OBD II)		AIS 137 Part 4	
115B	B.I	Mass Emission standard for CNG Vehicles. For O.E. CNG Dedicated Vehicle made by vehicle manufacturers		-	
	E	CNG Safety Checks for CNG kit components and installation		-	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1), (2) & (3)	Speed Governor (SLF) (ECU- M/s Alternative Fuel Systems Inc. Canada, ID- 20-05036)		AIS-018:2001	
ICAT Ref No.	2022 - 0294 (IOCS Ref: 166323)				
Engine Report No.	CT0ES 0024 DT. 17.01.2023				
Noise Report No.	CT0VP 0122 DT. 04.02.2020 & CT0VS 0733 Dt. 03.05.2023				
Horn Inst. Report No.	CT0VM 1806 DT. 01.11.2017				

AUTHORISED SIGNATORY

		
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR	 Page 2 of 8