



C	A	O	B	0016	F03	V01
---	---	---	---	------	-----	-----

Date : 05th July 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front / Rear	Make		
			3.00-10, 42 J	M/s. Ralson	
			90/90-10, 50 J	Cavendish (JK)	
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Below 7kW)	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		86.9 dB(A)
			Performance		IS 1884:1993
120	(2)	Pass by Noise	Limit :	75 dB(A)	IS 3028:1998
			Observed :	59 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle	Pillion Handhold	IS 14495:1998	
	(2)		Footrests	AIS 148:2018	
	(4)		Stand	AIS 146:2018	
	(5)		External Projection	AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation	AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2023-0269 (IOCS Ref.- 166729)
Power Test Report No.	CTOES 0120 dt. 02.03.2023
Noise Report No.	CTOVS 0864 dt. 30.05.2023
Horn Inst. Report No.	CTOVO 0062 dt. 15.01.2019

AUTHORISED SIGNATORY		
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER		SAURABH DALELA DIRECTOR
		Page 2 of 4