



**C A S B 0708**





**Date : 25<sup>th</sup> July 2023**

**ANNEXURE - I**

| Rule No. | Sub Rule(s)                                 | Compliance Verified For  |                       | Standard                      |              |
|----------|---|--|-----------------------|-------------------------------|--------------|
| 93       | (1)(A), 1(B), 2                             | Motor vehicle width, length and height   |                       | -                             |              |
| 94       | (1), (2) & (3)                              | Condition of tyres   |                       | -                             |              |
| 95       | (1), (2), (3), (4), (5) & (6)<br>(Tubeless) | Size & ply rating of tyres   |                       | IS 15627:2005 & AIS-050:2004  |              |
|          |   | Front/Rear   | Make                  |                               |              |
|          |   | 90/90 12 54 L  | Ralson                |                               |              |
|          |   | 90/90 12 54 J  | TVS, CEAT             |                               |              |
| 96       | (1), (2), (3), (4)(ib), (7)(c) & (8)        | Brakes with CBS  |                       | IS-14664:2010                 |              |
| 102      | (1), (2) & (3)                              | Signaling devices, direction indicators and stop lights  |                       | -                             |              |
| 103      | (1)   | Position of the indicator  |                       | -                             |              |
| 104      | (1) & (4)                                   | Fitment of reflectors  |                       | AIS-057 (Rev. 1): 2010        |              |
| 105      | (1)(bb), (2)(i) & (4)                       | Lamps  |                       | -                             |              |
| 106      | (1)   | Deflection of lights   |                       | -                             |              |
| 108      | (1)   | Use of red or white lights   |                       | -                             |              |
| 111      | -   | Prohibition of spotlights etc.   |                       | -                             |              |
| 117      | (1) & (2)                                   | Speedometer  |                       | IS 11827:2008                 |              |
| 119      | (1) & (2)                                   | Installation (Below 7kW)   |                       | IS 15796:2008                 |              |
|          |   | Limit :  | 83 dB(A) to 112 dB(A) |                               |              |
|          |   | Observed :   | 89.7 dB(A)            |                               |              |
|          |   | Performance  |                       |                               | IS 1884:1993 |
| 120      | (2)   | Pass by Noise  | Limit :               | 75 dB(A)                      | IS 3028:1998 |
|          |   |  | Observed              | 59 dB(A)                      |              |
| 122      | (1) & (2)                                   | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) |                       | AIS-065:2005                  |              |
| 123      | (1)   | Safety devices in motor cycle  | Pillion Handhold      | IS 14495:1998                 |              |
|          | (2)   |  | Footrests             | AIS 148:2018                  |              |
|          | (4)   |  | Stand                 | AIS 146:2018                  |              |
|          | (5)   |  | External Projection   | AIS 147:2018                  |              |
| 124      | Refer Annexure-IA & IB                      | Safety standards of components as applicable   |                       | -                             |              |
| 125      | (2)(a)                                      | Rear View  | Specifications        | AIS-001 (Part 2) (Rev.1):2011 |              |
|          |   | Mirror   | Installation          | AIS-002 (Part 2) (Rev.1):2011 |              |

|                              |                              |
|------------------------------|------------------------------|
| <b>ICAT Ref No.</b>          | 2022-0610 (IOCS Ref: 159349) |
| <b>Power Test Report No.</b> | CTOPR 0956 dt. 08.08.2022    |
| <b>Noise Report No.</b>      | CT0VS 0988 dt 13.06.2023     |
| <b>Horn Inst. Report No.</b> | CT0VS 0993 dt 13.06.2023     |

**AUTHORISED SIGNATORY**

|  |  |   |   |
|--|--|---|---|
| <br><b>MADHUSUDAN JOSHI</b><br>DEPUTY GENERAL MANAGER | <br><b>INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY</b><br>Innovation • Service • Excellence<br>MANESAR | <br><b>SAURABH DALELA</b><br>DIRECTOR | <br><b>ICAT</b><br>Innovation • Service • Excellence |
|--|--|---|---|

Page 2 of 4