







C A S B 0763

Date : 11th August 2023

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard | |
|----------|---------------------------------------------|--------------------------------------------------------------------------------------------------------------------|-------------------------------|------------------------------------|-----------------------|
| 93 | (1)(A), (1)(B), (2) | Motor vehicle width, length and height | | - | |
| 94 | (1), (2), (3) | Condition of tyres | | - | |
| 95 | (1), (2),(3), (4), (5) & (6) (Tube Type) | Size & ply rating of tyres | | IS 15627:2005 & AIS-050-2004 | |
| | | Make | TVS | | |
| | | Front/ Rear | 3.75-12, 60J 90x90-12, 54J | | |
| | | | 3.75-12, 66B 90x90-12, 54J | CEAT | |
| 96 | (1), (2), (3), (4)(i), (7)(b) | Brakes | | IS 14664:1999 | |
| 99 | - | Forward and backward motion | | - | |
| 100 | (1),(2),(3) | Safety glass | | NA | |
| 101 | (1),(2) | Windscreen Wiper | | NA | |
| 102 | (1), (2) | Signaling devices, direction indicators and stop lights | | - | |
| 103 | (1), (2) | Position of the indicator | | - | |
| 104 | (1)(v),(4) | Fitment of reflectors & reflective tapes | | AIS-057(Rev.1):2010 & AIS-090-2005 | |
| 105 | (1)(b), (3), (4), (5), (7) | Lamps | | - | |
| 106 | (1) | Deflection of lights | | - | |
| 108 | (1) | Use of red or white lights | | - | |
| 109 | - | Parking lights | | - | |
| 110 | - | Lamps for three wheelers | | - | |
| 111 | - | Prohibition of spotlights etc. | | - | |
| 119 | (1) & (2) | Horns | Installation | IS 15796:2008 | |
| | | | Limit : | | 83 dB(A) to 112 dB(A) |
| | | | Observed : | | 92.4 dB(A) |
| | | | Performance | IS 1884:1993 | |
| 122 | (1) & (2) | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) | | AIS-065-2005 | |
| 124 | - | Safety standards of components as applicable | | Refer ANNEXURE - IA & IB | |
| 125 | (2)(a) | Rear View | Specifications | AIS-001 (Part-2)Rev.1:2011 | |
| | | Mirror | Installation | AIS-002 (Part-2)Rev.1:2011 | |

| | |
|-----------------------|--------------------------------------------------------------------------------|
| ICAT Ref No. | (2023-0192, IOCS : 166383) |
| Power Test Report No. | ARAI/AED/20202021/3000016391/CT/5123 dt. 19.03.2021, CTOPS 0707 dt. 02.06.2023 |
| Horn Inst. Report No. | CTOVM 0256 dt. 07.03.2017 |

| | | | | |
|-------------------------------------------------------------------------------------|---------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| AUTHORISED SIGNATORY | |  |  |  |
|  | MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER | | | |