



C A S B 841

Date : 15th September 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless, Crossply)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front / Rear	90/90-12 54J		Srichakra
96	(1), (2), (3), (4)(ib), (4-A), (7)(c) & (8)	Brakes with GBS		IS-14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Below 7kW)	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		91.2 dB(A)
120	(2)	Pass by Noise	Performance	IS 1884:1993	
			Limit :	64.5 dB(A)	
120	(2)	Pass by Noise	Observed :	IS 3028:2018	
				dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle	Pillion Handhold	IS 14495:1998	
	(2)		Footrests	AIS 148:2018	
	(4)		Stand (Prop)	AIS 146:2018	
	(5)		External Projection	AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation	AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2023-0904 (IOCS Ref: 169222)
Power Test Report No.	ARAI/AED/20232024/4400045607/CT/0696 dt. 17.07.2023
Noise Report No.	CT0VS 1539 dt. 15.09.23
Horn Inst. Report No.	ARAI/SHL/CT/APX-23240748/0341 dt. 21.07.2023

AUTHORISED SIGNATORY

VIKAS SADAN DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR	Page 2 of 4