



C	A	S	B	0704	F01
---	---	---	---	------	-----

Date : 10th October 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front / Rear	110/70-12, 47P		MRF, CEAT
96	(1), (2), (3), (4)(ib), (4-A), (7)(c) & (8)	Brakes with CBS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		92.7 dB(A)
120	(2)	Pass by Noise	Performance	IS 1884:1993	
			Limit :		75 dB(A)
			Observed :		68 / 70 dB(A)
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1) (2) (4) (5)	Safety devices in motor cycle	Pillion Handhold	IS 14495:1998	
			Footrests	AIS 148:2018	
			Stand (Prop)	AIS 146:2018	
			External Projection	AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation	AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2023-1136 (IOCS Ref: 170263)
Power Test Report No.	CT0ES 0449 dt 29.09.2023
Noise Report No.	CT0VS1171 dt 21.07.2023
Horn Inst. Report No.	CT0VS1176 dt 21.07.2023

AUTHORISED SIGNATORY		
VIKAS SADAN DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR	Page 2 of 4