



C	A	S	B	0704	F01
---	---	---	---	------	-----


Date : 10<sup>th</sup> October 2023

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard		
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-		
94	(1), (2) & (3)	Condition of tyres		-		
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004		
		Front / Rear	110/70-12, 47P		MRF, CEAT	
96	(1), (2), (3), (4)(ib), (4-A), (7)(c) & (8)	Brakes with CBS		IS 14664:2010		
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-		
103	(1)	Position of the indicator		-		
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010		
105	(1)(bb), (2)(i) & (4)	Lamps		-		
106	(1)	Deflection of lights		-		
108	(1)	Use of red or white lights		-		
111	-	Prohibition of spotlights etc.		-		
117	(1) & (2)	Speedometer		IS 11827:2008		
119	(1) & (2)	Horns	Installation (Above 7kW)		IS 15796:2008	
			Limit :	87 dB(A) to 112 dB(A)		
			Observed :	92.7 dB(A)		
120	(2)	Pass by Noise	Performance		IS 1884:1993	
			Limit :	75 dB(A)		
			Observed :	68 / 70 dB(A)		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005		
123	(1)	Safety devices in motor cycle	Pillion Handhold		IS 14495:1998	
	(2)		Footrests		AIS 148:2018	
	(4)		Stand (Prop)		AIS 146:2018	
	(5)		External Projection		AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-		
125	(2)(a)	Rear View	Specifications		AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation		AIS-002 (Part 2) (Rev.1):2011	

<b>ICAT Ref No.</b>	2023-1136 (IOCS Ref: 170263)
<b>Power Test Report No.</b>	CT0ES 0449 dt 29.09.2023
<b>Noise Report No.</b>	CT0VS1171 dt 21.07.2023
<b>Horn Inst. Report No.</b>	CT0VS1176 dt 21.07.2023

**AUTHORISED SIGNATORY**

		
--	---	--