



C A S B 0899

Date : 18th October 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), (1)(B), 2	Motor vehicle width, length and height			-
94	(1), (2) & (3)	Condition of tyres			-
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Front / Rear	Size & ply rating of tyres 90/90-12,54J	Make M/s Cavendish Industries Ltd(JKTyre)	IS 15627:2005 & AIS-050:2004
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes with CBS			IS 14664:2010
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights			-
103	(1)	Position of the indicator			-
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010
105	(1)(bb), (2)(i) & (4)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
111	-	Prohibition of spotlights etc.			-
117	(1) & (2)	Speedometer			IS 11827:2008
119	(1) & (2)	Horns	Installation (Below 7kW) Limit : 83 dB(A) to 112 dB(A) Observed : 84.4 dB(A)	IS 15796:2008	
			Performance	IS 1884:1993	
120	(2)	Pass by Noise	Limit : 75 dB(A) Observed : 61 dB(A)	IS 3028:1998	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005
123	(1)	Safety devices in motor cycle		Pillion Handhold	IS 14495:1998
	(2)			Footrests	AIS 148:2018
	(4)			Stand	AIS 146:2018
	(5)			External Projection	AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-
125	(2)(a)	Rear View Mirror	Specifications Installation	AIS-001 (Part 2) (Rev.1):2011 AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2023-1317 (IOCS Ref: 170169)
Power Test Report No.	CTOES 0370 dt. 04.08.2023
Noise Report No.	CTOVS 1570 dt. 25.09.2023
Horn Inst. Report No.	CTOVS 1572 dt. 25.09.2023

AUTORISED SIGNATORY			
VIKAS SADAN =	MANESAR	SAURABH DALELA	Page 2 of 4
DEPUTY GENERAL MANAGER		DIRECTOR	

