








|   |   |   |   |      |     |     |
|---|---|---|---|------|-----|-----|
| C | A | L | B | 0074 | F01 | V01 |
|---|---|---|---|------|-----|-----|

Date : 01<sup>st</sup> November 2023

**ANNEXURE - I**

| Rule No.     | Sub Rule(s)                                  | Compliance Verified For  |                | Standard                          |                            |
|--------------|--|--|----------------|-----------------------------------|----------------------------|
| 93           | (1)(A), (1)(B), (2)                          | Motor vehicle width, length and height   |                | -                                 |                            |
| 94           | (1), (2), (3)                                | Condition of tyres   |                | -                                 |                            |
| 95           | (1), (2), (3), (4), (5) & (6)<br>(Tube Type) | Size & ply rating of tyres   |                | IS 15627:2005 &<br>AIS-050-2004   |                            |
|              |  | Front/<br>Rear   | 3.75-12 66B    |                                   | Ralson                     |
|              |  |  | 3.75-12, 66B   |                                   | CEAT                       |
|              |  |  | 3.75-12, 66E   |                                   | MRF Ltd                    |
| 3.75-12, 60J | TVS  |  |                |                                   |                            |
| 96           | (1), (2), (3), (4)(i), (7)(b)                | Brakes   |                | IS 14664:1999                     |                            |
| 99           | -  | Forward and backward motion  |                | -                                 |                            |
| 100          | (1), (2), (3-A) & (3)(c)                     | Safety glass as amended by GSR 784(E) – Ref. ANNEXURE-IB   |                | NA                                |                            |
| 101          | (1)  | Windscreen Wiper   |                | NA                                |                            |
| 102          | (1), (2)                                     | Signaling devices, direction indicators and stop lights  |                | -                                 |                            |
| 103          | (1), (2)                                     | Position of the indicator  |                | -                                 |                            |
| 104          | (1)(v), (4)                                  | Fitment of reflectors & reflective tapes   |                | AIS-057(Rev.1):2010 & AIS090-2005 |                            |
| 105          | (1)(b), (3), (4), (5), (7)                   | Lamps  |                | -                                 |                            |
| 106          | (1)  | Deflection of lights   |                | -                                 |                            |
| 108          | (1)  | Use of red or white lights   |                | -                                 |                            |
| 109          | -  | Parking lights   |                | -                                 |                            |
| 110          | -  | Lamps for three wheelers   |                | -                                 |                            |
| 111          | -  | Prohibition of spotlights etc.   |                | -                                 |                            |
| 119          | (1) & (2)                                    | Horns  | Installation   |                                   | IS 15796:2008              |
|              |  |  | Limit :        | 83 dB(A) to 112 dB(A)             |                            |
|              |  |  | Observed :     | 96.5 & 88.5 dB(A)                 |                            |
|              |  |  | Performance    |                                   | IS 1884:1993               |
| 122          | (1) & (2)                                    | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) |                | AIS-065-2005                      |                            |
| 124          | -  | Safety standards of components as applicable   |                | Refer ANNEXURE - IA & IB          |                            |
| 125          | (2)(a)                                       | Rear View  | Specifications |                                   | AIS-001 (Part-2)Rev.1:2011 |
|              |  | Mirror   | Installation   |                                   | AIS-002 (Part-2)Rev.1:2011 |

|                       |   |
|-----------------------|---|
| ICAT Ref No.          | 2023-1167 (IOCS No.170126)                              |
| Power Test Report No. | CT0PS 0392 dt. 07.03.2023 & CT1ES0054E01 dt. 30.05.2023 |
| Horn Inst. Report No. | CT1VS 0819 dt. 19.05.2023                               |

|   |   |   |  |   |
|---|---|---|--|---|
| <b>AUTHORISED SIGNATORY</b>   |   |  |  |  |
|  |  |   |  |   |
| <b>VIKAS SADAN</b><br>DEPUTY GENERAL MANAGER  | <b>SAURABH DALELA</b><br>DIRECTOR   |   |  | Page 2 of<br>3  |